

SERVICE ACTION

Reference number:	SA-01-1143	Issued: 21 March, 2019
Subject:	Lamy Pen Holder – Incorrect Colour	
Model(s):	Vanquish Zagato	
VIN range:	Refer to the separately published list of Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

The colour of the Lamy Pen Holder is incorrect on some Vanquish Zagato vehicles. Do the procedure that follows if a vehicle has a Lamy Pen Holder of the incorrect colour.

Workshop Procedure

CAUTION: MAKE SURE THAT NO DAMAGE OCCURS TO THE VEHICLE BODYWORK. TOOLS CAN CAUSE DAMAGE IF SUFFICIENT PROTECTION IS NOT USED. USE LEATHER SKI-SLOPE PROTECTION ON THE CENTRE CONSOLE.

1. Remove the Centre Stack Assembly (refer to Workshop Manual Procedure 15.01.CB).
2. Remove the Lamy Pen Holder (refer to Workshop Manual Procedure 18.03.AE and Figure 1).




Figure 1

3. Install a new Lamy Pen Holder of the correct colour (refer to Workshop Manual Procedure 18.03.AE).
4. Install the Centre Stack Assembly (refer to Workshop Manual Procedure 15.01.CB).

Part Data

Description	Part Number	Quantity
LAMY PEN HOLDER	HD3Y-56051-BA	1

Warranty Data**Procedure and Labour Time**

Description	Labour Time
Replace Lamy Pen Holder	1.25 hours

Please Note:

When you have completed this Service Action, make sure that you make an entry in Section A of the Vehicle Owner's Guide to show that the procedure is completed.

If you have any questions related to this Service Action, please contact: Aston Martin Technical Services
on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
or contact your After Sales Manager.

The English version of this Service Action is written in
Simplified Technical English to ASD-STE100™.