

SERVICE ACTION

Reference number:	SA-01-1557	Issued: 14 December, 2021
Subject:	DBX Swing Clearance Check	
Model(s):	DBX	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

Aston Martin has identified some DBX vehicles that must have a swing clearance check completed to make sure the front doors have the correct clearance when opened.

Do the workshop procedure that follows to do a swing clearance check of the front doors, and if necessary complete the applicable adjustment procedure.

Workshop Procedure

1. Do a swing clearance check of the front doors (refer to Workshop Manual Procedure 22.02.CP).
2. If adjustment is not necessary, no further action is necessary.
3. If adjustment is necessary, refer to the applicable adjustment procedure in the workshop manual.

Warranty Data

Note: Before the warranty repair is started, photograph the affected area(s). The photograph(s) must be attached to the repair order for audit purposes.

Tier A

Description	Labour Time
Swing Clearance Check	0.10

Tier B

Description	Labour Time
Check Clearance and Adjust Bonnet	0.35

Tier C

Description	Labour Time
Check Clearance and Adjust 1 Front Door	0.90

Tier D

Description	Labour Time
Check Clearance and Adjust Both Front Doors	1.70

Tier E

Description	Labour Time
Check Clearance and Adjust 1 Front Wing	0.90

Tier F

Description	Labour Time
Check Clearance and Adjust Both Front Wings	1.70

Tier G

Description	Labour Time
Check Clearance and Adjust 1 Front Door and 1 Front Wing	1.70

Tier H

Description	Labour Time
Check Clearance and Adjust 1 Front Door and Both Front Wings	2.50

Tier I

Description	Labour Time
Check Clearance and Adjust Both Front Doors and 1 Front Wing	2.50

Tier J

Description	Labour Time
Check Clearance and adjust Both Front Doors and Both Front Wings	3.30

Tier K

Description	Labour Time
Check Clearance and Adjust Bonnet and 1 Front Door	1.15

Tier L

Description	Labour Time
Check Clearance and Adjust Bonnet and Both Front Doors	1.95

Tier M

Description	Labour Time
Check Clearance and Adjust Bonnet and 1 Front Wing	1.15

Tier N

Description	Labour Time
Check Clearance and Adjust Bonnet and Both Front Wings	1.95

Tier O

Description	Labour Time
Check Clearance and Adjust Bonnet, 1 Front Door and 1 Front Wing	1.95

Tier P

Description	Labour Time
Check Clearance and Adjust Bonnet, 1 Front Door and Both Front Wings	2.75

Tier Q

Description	Labour Time
Check Clearance and Adjust Bonnet, Both Front Doors and 1 Front Wing	2.75

Tier R

Description	Labour Time
Check Clearance and Adjust Bonnet, Both Front Doors and Both Front Wings	3.55

Please Note:

When you have completed this Service Action, make sure that you make an entry in Section A of the Vehicle Owner's Guide to show that the procedure is completed.

Yours faithfully



John Cranfield

Senior Manager - Client Technical Services

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.